

7/25/03

Final Close Out Report Former Nutting Truck and Caster Company Site Faribault, Minnesota

Table of Contents

1.0 Introduction	1
2.0 Summary of Site Conditions	2
2.1 Regulatory History	2
2.2 Soil Operable Unit Response Action.....	3
2.3 Groundwater Operable Unit Response Action	3
2.3.1 Applicable Criteria	4
2.3.2 Groundwater Response Action Effectiveness	5
2.4 Community Involvement.....	5
2.5 Property Redevelopment	6
3.0 Demonstration of Cleanup Activity QA/QC	7
4.0 Monitoring Results	8
5.0 Summary of Operations and Maintenance	10
6.0 Summary of Remediation Costs.....	11
7.0 Protectiveness.....	12
8.0 Five-Year Review.....	13
9.0 Bibliography.....	14

List of Tables

Table 1	Groundwater Elevations 1988-2002
Table 2	Volatile Organic Compounds - Historical Summary

List of Figures

Figure 1	Site Location
Figure 2	Site Plan and Disposal Pit Location
Figure 3	Water Table Contour Map – November 1988
Figure 4	Water Table Contour Map – May 2002
Figure 5	Monitoring Well Locations

